



CLEAR VIEW® CAPS-Grip Trac

INSTALLATION INSTRUCTIONS

- Remove OEM Cap.
- Remove O-ring and allow oil to completely drain.
- Inspect & clean present o-ring, if damaged, flattened or not acceptable for reuse, replace.
- Lightly oil O-ring before installing, bolt clear cap to the hub and tighten bolts to 40-50 inch pounds.
- Replace oil in hub to manufacturer's specifications.

*Use only soap and water to clean caps, no solvents (solvents can cause clouding and premature failure of caps).
Solvent use will void warranty*

PARTS LIST:

Part	Desc	Qty
K 7120-GT	Kile Clear View Cap	20
K GT047	K047 Oring	20
K GT161	K161 Oring	20

